



COS
Monthly Status Review
November 6, 2002
NASA/GSFC



COS
Monthly Status Review



Agenda

Progress Summary Since Last Monthly	J. Andrews
GN2 Alignment Update	J. Green
UCB FUV Detector Programmatic Status	J. Andrews
UCB FUV Detector Technical Status	O. Siegmund
Software/Ops	J. Andrews
Schedules	J. Andrews
Descope Report	J. Andrews
Upcoming Events/Activities	J. Andrews
CU Issues & Resolution Plan	J. Andrews
STScI Presentation	K. Sembach
BATC Presentation	R. Higgins
Financial Splinter	GSFC/Ball/CU



Progress Summary Since Last MSR

- Supported and completed GN2 alignment check.
- Continued COS TV and calibration planning.
- Initiated assembly of FUV-02 at UCB.
- Held Science Team Meeting on 10/31 – 11/1.





Nitrogen Testing of COS

- Under N₂ purge and with FUV detector door closed, end-to-end testing of COS with RASCAL was performed.
- RASCAL spectra in NUV channels indicated residual aberrations in end-to-end system and input misalignments.
- Several small misalignments within COS were identified and corrected.
- System is performing nominally.

Overview of FUV Detector Assemblies


- **DEB - (Detector Electronics Box)**
 - DCE (Detector Control Electronics)
 - TDCs (Time-to-Digital Converters)
 - HVPS (High Voltage Power Supply)
 - LVPC (Low Voltage Power Converter)
- **DVA - (Detector Vacuum Assembly)**
 - VHA (Vacuum Housing Assembly)
 - Detector Door Mechanism
 - Ion Pump Assembly
 - DBA (Detector Backplate Assembly)
 - Amplifiers
 - HVFM (High Voltage Filter Module)





FUV Detector Subsystem Block Diagram

- UCB is under contract to deliver 1 flight FUV detector subsystem (FUV-01) and 1 flight-spare detector subsystem (FUV-02).



TA - Timing Amplifier
CA - Charge Amplifier
TDC - Time-to-Digital Converter
TH - Threshold Ckt
EF - Event Formatter
RR - Round Robin Arbitrator

FEC - Front End Counter
PRC - Preamp Reset Counter
DEC - Digitized Event Counter
SDC - Science Data Counter
HR - Hardware Reset Ckt

GG 11/99



FUV Detector Overview

- FUV-01 was delivered to Ball on Wednesday, July 31st.
- FUV-01 has operated flawlessly since its integration into the instrument and has accumulated 72 hours of instrument level run-time (>50% of that time was with HV on).
- FUV-02 is in processing now at UCB and upon completing environmentals it will go into storage at CU.



COS

Monthly Status Review



FUV Detector Verification Testing Summary



Unit	Functional Testing	Performance Testing	EMI/EMC	Sine Burst	Random Vibe	Thermal-Vac	Contamination Certification
FUV-01 DVA	C	C	@SS	A - C	A - C	@SS	@SS
FUV-01 DEB	C	C	@SS	Q - C	Q - C	@SS	@SS
FUV-01 SS	C	C	C	@Comp	@Comp	8-cycles	C
FUV-02 DVA	P	P	N/R	Q - P	Q - P	@SS	@SS
FUV-02 DEB	C	C	N/R	A - P	A - P	@SS	@SS
FUV-02 SS	P	P	N/R	@Comp	@Comp	8-cycles	P
DVA Surrogate (1)	C	N/R	N/R	C	C	N/R	N/R
DVA Surrogate (2)	C	N/R	N/R	C	C	C	N/R

C Complete
 @SS At Subsystem
 A Acceptance Levels
 Q Qualification Levels
 N/R Not Required
 P Planned
 (1) Old Door Mechanism
 (2) New Door Mechanism

— DVA-02 to see qual-level vibe at LMMS
 — FUV-02 to see 8 cycle T/V at CU
 — DEB-01 to see 1-axis workmanship vibe at Ball

COS FUV Detector Systems

- Detector DEB
- Detector Head






Flight FUV01 Detector System

Completed thermal vacuum at
CU, delivered to Ball 7/31.

Post delivery functional tests
nominal.

Cleanliness certification at Ball
completed successfully.

Alignment tests in done.





Status for FUV01

- Ship to CU -- Arrived 7/19, Thermal vacuum test -, begun 7/23
- Thermal vacuum finished successfully 7/29, including
- Cleanliness certification at CU
- Delivered to Ball - 7/31, functional test completed - OK
- Repeated cleanliness certification at Ball - OK
- Alignment tests completed at Ball
- Two minor repairs to be done next week,
 - Replace torn HVFM connector socket rubber boot
 - Replace rotating jack post on one "D" connector on DEB
 - Workmanship shake of DEB planned at Ball




UCB FUV02, Flight Backup Detector, Status


- **DEB & Harnesses**
 - Completed and tested successfully.
- **Detector integrated with Vacuum Housing Assembly .**
 - Completed functional test and MCP “deep” scrub
 - New cathode deposition done, QE’s measured better than FUV01.
 - Completed post cathode mini-scrub & QE check (minor drop, ~7%)
 - Experienced strong QE grid field emission during QE test
 - Removed and completed “grid wash”, field emission now gone
 - QE remeasured - no changes - but need to repeat mini-scrub
 - While preparing for mini-scrub noticed small VHA leak at full atmosphere
- **Vacuum Housing Assembly (VHA)**
 - Small, intermittent, leak discovered at door/VHA seal
 - Re-greased “O” ring and seal is OK - But investigating cause/remedy
 - Initial evaluation shows known sag of VHA (0.005”) at atmosphere but also indicates a small (0.007”) bowing of the VHA seal at one specific area - we have proposed remedies to the project.

FUV02, New Cathode Deposition


FUV02 detector with QE grid installed



New CsI cathode, A side



New CsI cathode, B side





New cathode is in accord with the best CsI we have previously done on COS microchannel plates



FUV02 New Photocathode QE measurements



QE for FUV02 is ~20% better than FUV01 on average





FUV02 Deep Scrub Gain Curve History



Gain decreases due to scrub which is compensated by increasing the MCP voltage
We accomplished the scrub before a cathode deposition to avoid QE degradation!





FUV02 Deep Scrub Gain Curve History

The gain decreased as a function of extracted charge then increased and stabilized,
We expect less than x2 gain change per coulomb (COS spec)





FUV02, Flight Backup Detector Actions


- **Resolve VHA seal leak issue**
- **Re-install in test chamber, perform QDE test**
- **Mini scrub**
- **QDE calibration and full functional test,**
- **Flat field test**
- **Vibration test and post vibration functional**
- **Pack and ship to CU**
- **Thermal vacuum test at CU**
- **Cleanliness certification and delivery to Ball**




FUV02 VHA completed assembly

Door assembly

Motor assembly



Ion pumps




Pumping port

Top of vacuum housing



FUV02 Door assembly attached to VHA

Lower (seal)
door




VHA

Pumping
Port



COS
Monthly Status Review

Door assembly attached to VHA




Door assembly attached to VHA - inspection and metrology

Measurement of VHA surface with
& without atmosphere differential

VHA seal area,
compressed "O" ring gap



Pumping port





FUV02, VHA Seal Leak, Status

Vacuum Housing Assembly (VHA)

- While preparing for mini-scrub noticed small VHA leak (via ion pump current) only at full atmosphere pressure differential
- First leak check showed no leak
- After additional door operation at vacuum, small, intermittent, leak discovered at door/VHA seal.
- Inspected and re-greased “O” ring and now seal is OK - But we have investigated cause/remedy for the leak
- Initial evaluation confirms known sag of VHA (0.005”) at atmosphere differential, but also indicates a (0.007”) bowing of the VHA seal at one specific area - center of VHA seal area across from pump port.



FUV02, VHA Seal Leak, Status

- Door seal gap is set at $\sim 0.007''$ during door installation
- We have four Vacuum Housings
 - FUV01 - records indicate door seal gap is $\sim 0.007''$ and uniform
 - FUV02 - seal surface shows extra dip of $\sim 0.007''$ at center/port side
 - ETU - seal surface shows extra dip of $\sim 0.003''$ at center/port side
 - Spare - seal surface is flat to $0.001''$
- FUV01, FUV02, & ETU all have SMA connectors and pump ports welded on. Spare has not been welded.
- Specification for Vacuum Housings is $< 0.002''$ seal flatness
- Measurements of Spare shows flat top surface everywhere
- Measurements of ETU and FUV02 show dips at center/port side
 - $0.007''$ for FUV02, $0.003''$ for ETU
 - Also $0.0015''$ dip at SMA connector side for FUV02
- Measurements of FUV02 seal gap
 - At air, $0.008''$ at corners, $0.013''$ at center /port side
 - At vacuum differential, $0.007''$ at corners, $0.014''$ at center /port side



FUV02, VHA Seal Leak, Status

- We have two doors from Ball, FUV01 and FUV02
- Both were measured flat to better than $\sim 0.001''$
- We suspect that the FUV02/ETU VHA distortions were incurred when the pumping ports and SMA feedthroughs were welded in.
- After “o”ring regrease the VHA now seals and there is no leak
- **Door/VHA has accumulated >40 successful operations,**
 - **There is probably a re-distribution of grease on the “o” ring with ops**
 - **Leak appears only at 1 Atm differential, after many operations**


Current Situation

- FUV02 DBA (detector) is currently stored separately under vacuum
- FUV02 VHA is fully assembled and under vacuum with ETU DBA
- We have investigated many different ways of resolving the problem with emphasis on maintaining the FUV02 integrity
- Our preferred resolution involves re-surfacing of the seal door to match the VHA shape



COS

Monthly Status Review



FUV02 VHA with ion pumps

Ion grid SMA location


~0.0015" dip

~0.007" dip

Pumping port weld area



VHA with door mechanism removed





FUV02, VHA Seal Leak, Plan


- Metrology gives us a detailed measure of the shape of the seal surface
- Remove FUV02 seal door and substitute ETU to maintain vacuum
- Make door blanks and resurface them using EDM + polish
- Check the measurements & seal with blanks + FUV02 VHA
- Resurface the FUV02 seal door using EDM + polish
- Re-install the FUV02 seal door and re-shim the door mechanism to achieve the correct seal gap, and measure with Atm differential
- Run door operation tests and re-verify seal and metrology
- Re-install detector/DBA and continue with FUV02 completion plan
- This minimizes disassembly of VHA (none on DBA) and risk to assy
- Achieves desired uniform seal gap/"o"ring compression
- Minimizes time & cost to effect the resolution
- Also obtain "profiled" "O" rings to "accommodate" gap (backup)
- Make spare door to accommodate AU options



COS

Monthly Status Review


Lower door detached from upper door (links disconnected)



Pumping port



VHA with door mechanism removed





Software/Ops Update

- Brownsberger and Beland continue their presence at Ball supporting the SW/OPS efforts.
 - Brownsberger is working CS/DCE activities
 - Beland is working Target Acquisition component testing.
- CEDAR has been stable for some months and is supporting GN2 alignments at Ball.



COS
Monthly Status Review



COS Schedule Milestones for CU/UCB

Task	Status
CALCOS Software Development	On-going. Completion by ~ TV-2 mos
Cal/FF SS Retest	12/02
Complete FUV-02	TBD – pending vacuum seal fix
Complete COS TV/TB Plan	12/02



COS Descope Issues (No Changes Since Last MSR)

- The COS IDT has been asked to develop and track a descope plan which, if implemented, can be used to control future cost growth and/or schedule difficulties.
- At the beginning of the COS development effort, late CY97 and early CY98, we prepared and presented several descope options. At that time we descope the following:
 - Reduced the MEB SRAM buffer memory
 - Fewer NUV/FVU optics/grating spares
 - No parallel technology path for NUV gratings
 - Reduced I&T/calibration effort
 - Baselined environmentals at GSFC



COS Descope Tracking List

Candidate De-Scope	Trigger Date	Resource Saved*	Impacts
Eliminate FUV Detector detailed resolution tests	Implemented	2 weeks	Knowledge of detector
Eliminate FUV Detector detailed QE tests	Implemented	2 weeks	Knowledge of detector
Eliminate FUV Detector deep FF tests	Implemented	3 weeks	Knowledge of detector
Make DCE Op Code non-uploadable	Too late	---	Higher risk, Ops
Early transition of FSW to Code 582	Too late	---	Ops
Remove Redundant Cal/FF Elements	Too late	---	Higher risk, Ops
Remove/reduce memory	Too late	---	Ops
Remove NUV gratings from OSM2	Too late	---	Degraded science
Drop NUV channel	Too late	---	Degraded science
Remove NCM3 optics	Too late	---	Degraded science, Ops
Eliminate Aperture Mechanism	Too late	---	Ops, Obs. Efficiency, higher risk
Drop all Accum mode processing w/ Doppler	Too late	---	Degraded science
Drop spare FUV detector	Too late	---	Higher risk
Drop OSM1 capability (don't cover λ gap)	Too late	---	Degraded science
Reduce S/N requirement to 30 (no FF lamp)	Too late	---	Degraded science
Relax NUV resolution requirements below 20k	Too late	---	Degraded science
Remove on-orbit change-out capability	Too late	---	Higher risk
Drop dispersed light TA	Too late	---	Ops
No Ion Gauge	Too late	---	Higher risk, Ops
No external shutter	Too late	---	Ops
Change MSRs to QSRs	TBD	\$	Save trees
Eliminate Mechanism Lifetime tests	Too late	---	Higher risk
Reduce CDRLs	TBD	\$	Unknown
Drop G140L blazed effort	Implemented	---	Missed opportunity for improved science
Reduce G160M image testing	Too late	---	Higher risk

*The IPT has not yet done a detailed analysis to quantify actual \$ or time to be saved.



Upcoming Events/Activities

- Resolve FUV-02 vacuum leak.
- FUV-02 environmental testing.
- Continued COS TV and calibration planning and preparation.



Issues

- None